

Errata for 2021 National Standard Plumbing Code–New Jersey Edition 1st Printing

The following is a change that we found after the first printing of the *2021 National Standard Plumbing Code, Illustrated–New Jersey*. We do encourage you to make a note in your code book to ensure that the change is reflected. Thank you.

SECTION: 7.11.4 Service Sinks and Mop Receptors

Change paragraph b.) to read as follows:

b. Service sinks and mop receptors shall not be installed where walls and floors are not waterproof and do not have a smooth, readily cleanable surface. Refer to the International Building Code, Section ~~1209.2.2~~ 1210.2.2.

Updated 11/16/2022