

Errata For 2010 Green Plumbing and Mechanical Code Supplement – 1st Printing

The following is a list of changes that we found after the first printing of the 2010 Green Plumbing and Mechanical Code Supplement. These changes may or may not apply to your code book. However, we do encourage you to check your code book with this list to ensure that all of the changes are updated. Thank you.

Foreword New mailing address for United Association (UA).

IAPMO Green Technical Committee An affiliation for Jeffrey Ingertson has been added.

Chapter 5

Section 501.5.2 The first sentence contains a typographical error. Correct sentence to read: A maintenance log for gray water, rainwater, and on-site treated non-potable water systems is required to have a permit in accordance with Section 501.3 and shall be maintained by the property owner and be available for inspection.

Section 505.10.5 (page 21) Section number 505.10.5 is numbered incorrectly. Correct section number to read 504.10.5.

Section 505.11.2.2 Item (3) contains a typographical error in the third sentence. Correct sentence to read: No flow from a potable water outlet shall indicate that it is connected to the rainwater water system.

Chapter 7

Table 703.4.4.2(2) The first column heading contains a typographical error. Correct heading to read: Seal Level.

Section 703.5.1, Exception (4) Section number reference reads 703.5.6.2. Correct to read 603.5.3.

Chapter 8

Section 808.1.1 This section contains an editorial error. Correct section to read: Solvent cement, including one-step solvent cement, shall have a volatile organic compound (VOC) content of less than or equal to 490 g/l (grams/liter) for CPVC Cement, 510 g/l (grams/liter) for PVC Cement, and 325 g/l (grams/liter) for ABS Cement, as determined by the South Coast Air Quality Management District's Laboratory Methods of Analysis for Enforcement Samples, Method 316A.

Section 808.1.2 This section contains an editorial error. Correct section to read: Primer shall have a volatile organic compound (VOC) content of less than or equal to 550 g/l (grams/liter), as determined by the South Coast Air Quality Management District's Laboratory Methods of Analysis for Enforcement Samples, Method 316A.

Appendix A

Table A101.2(1) This table contains typographical errors in the fifth row of the table. Correct to read in column one: Lavatory Faucets in other than Residences, Apartments, and Private Bathrooms in Lodging Facilities (See Section 402.4.2).
Correct to remove footnote reference in column four.

Appendix C

Form MECH-3A (Page 2 of 3) Section A Functional Testing Requirements has been revised with correct column headings.