## Errata for 2018 Uniform Plumbing Code – 6<sup>th</sup> Printing

The following are changes that we found after the sixth printing of the 2018 Uniform Plumbing Code. These changes may apply to your code book. Thank you.

## Appendix I – IAPMO IS 31

Figure 3 – Revise the conversion under 689.5 at the bottom of the figure, from "(10.0)" to "(100.0)".





Figure 4 – Revise the conversion under 689.5 at the bottom of the figure, from "(10.0)" to "(100.0)".



4/19/2021