

**Summary of Changes**  
**between the updates dated March 23, 2010 and the August 23, 2011 of**  
**UL 1795, “Standard for Hydromassage Bathtubs”**  
**(4<sup>th</sup> edition dated August 5, 2009)**

There is no immediate impact on existing files. This revision of UL 1563 is being issued to:

- (a) update the electric shock limits for bathtub side controls and circuits in contact with the bathtub water;
- (b) clarify controls requirements for controls evaluated to UL 873 and add requirements to specify the use of controls that comply with the UL 60730 family of standards; and
- (c) delete Appendix A and specify component requirements in the body of the standard.

Revision summary:

- The following addresses Item (a).
  - Clause 5.20 was modified – Definition for Risk of Electric Shock.
  - Table 5.1 was added
  - Clause 52.1 was revised
  - Clause 5.2.2(d) was added
- The following addresses Item (b).
  - Clauses 5.6.1 to 5.6.8 were added to Definitions
  - Clauses 38.1.3, 39.2.1, 39.3.2 were revised
  - Clauses 27.5, 39.2.1.1 were added
  - Tables 38.1, 39.1, 39.2 were added
  - Tables 19.1 were revised
  - Section 39A and Appendix B were added
- The following addresses Item (c).
  - Section 2 and Appendix A were deleted
  - Section 7A was added
  - Clauses 13.2.9.1, 13.3.8, 15.1.1.1, 15.1.3.1, 22.7, 28A, 30.15, 30.16, 30.17, 33.6, 34.4, and 36.1.11 to 36.1.14 were added
  - Clauses 12.7, 13.2.1, 13.2.6, 22.1.2, and 28 have been revised