


# Errata for 2018 Uniform Plumbing Code Illustrated Training Manual – 2nd Printing

The following are changes that we found after the second printing of the *2018 Uniform Plumbing Code Illustrated Training Manual*. These changes may apply to your code book. Thank you.

## CHAPTER 3

Figure 310.1 Prohibited or Restricted Fittings – The commentary in the figure for “Sanitary Tee with Single or Double Side Inlet” should be corrected as follows:

Manufactured as single or double sanitary tee with ~~we~~ither single or double inlet. ~~Prohibited in drainage system if side inlets are straight pattern. Only a~~Allowed in drainage system if side inlets are drainage pattern. Must be installed in a vertical position in the drainage system. Either side inlet patterns may be used in vent system.



**FIGURE 310.1  
PROHIBITED OR RESTRICTED FITTINGS**