



**Summary of Substantive Changes
between Update No. 2 dated November 2015 and the 2011 edition including Update No. 1
dated September 2015 of
CSA B64 Series-11, “Backflow preventers and vacuum breakers”**

Presented to the IAPMO Standards Review Committee on April 11, 2015

General: The change to this series of standards are editorial and should not have an impact on currently listed products. The editorial changes are:

- Updated the front cover, title page, Technical Committee and Preface
- Updated to indicate the approval of the standard as a National Standard of Canada.
- Moved an informational note from Figure 1 to Figure 2 of CSA B64.1.4 stating that “A hose shall be connected to any secondary inlet and the end of the hose dipped into the reservoir”. (see CSA B64.1.4 Figures 1 and 2)